NPIC/TDS/D-1191-67 22 December 1967

MEMORANDUM FOR: Chief, Equipment Performance Staff, TDS

SUBJECT : Enclosure for blower on VG-1 Vacuum Easel

1. The blower on the VG-1 Vacuum Easel in the Photo Lab is noisy and thus produces an unsatisfactory working condition for those operating the equipment for prolonged periods.

The blower on the VG-1 Vacuum Easel in the Photo Lab is noisy and thus produces an unsatisfactory working condition for those operating the equipment for prolonged periods.

The blower on the VG-1 Vacuum Easel in the Photo Lab is noisy and thus produces an unsatisfactory working condition for those operating the equipment for prolonged periods.

The blower on the VG-1 Vacuum Easel in the Photo Lab is noisy and thus produces an unsatisfactory working condition for those operating the equipment for prolonged periods.

2. Attached is a sketch of a sound absorbing enclosure. Please fabricate this enclosure by 5 January 1967.

Development Start, TDS

Distribution:
Original & 1 - Addressee
3 - NPIC/TDS/DS

DECLASS REVIEW by NIMA/DOD

25X1A

25X1A

25X1A

25X1A